

Heel Pad Replacement - \$10 / pad

Sole Rubber Trim Replacement - \$15 / shoe

All New Straps on Both Shoes - \$200 / pair

Footbed Liner Replacement - \$15 / shoe

New Faux Leather Uppers - \$475 / pair

3-Hole (LOOK) Cleat Replacement - \$100 / shoe

Speedplay Cleat Replacement - \$100 / shoe

Mountain Bike Cleat Replacement - \$100 / shoe

New 3 hole Carbon Fiber Soles - \$475 / pair

New Speedplay Carbon Fiber Soles - \$525 / pair

Cleat Removal - \$35 (please remove your cleats)

*****SPD Carbon Mountain Bike Shoes, you must protect the carbon with either a Shimano Cleat Adaptors or Crank Brothers "Shields". If you do not use these items, the carbon could be damaged and the cleat area could crack and not be able to repair.**